








W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Design Mgr	Approval QC Inspector
			Initial Design Mgr	Action Description Design Mgr	Sign & Date			
05/09/14	2	1 piece the length 16.50 was 16.880	 05/09/14	ACCEPTABLE. MODIFY 17.02 TO 17.38.	 07-09-14	 0509.14	 0509.14	 0509.14

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

NOTE: Date & initial all entries

QA: N/C Closed: _____ Date: _____



DART AEROSPACE LTD	Work Order:	24007 B
Description: OUTER TUBE	Part Number:	1367-43001-229
Dwg: 1367-43001-229	Qty:	20 7
		Page of

Step	Location	Procedure	By	Date	Qty
1	DC	Issue Traveler	ML	05-07-02	17 10
2	MM	Machine manually perching B67-43001 Rev. B Material M6061T6R.750W065 <u>118483</u>	PMZ	05-09-06	7
3	QC2	Inspect parts as they come off the machine	PMZ	05-09-11	10
4	QC8	Second check	Er	05/09/14 05-09-12	7
5	MV	Debur	PMZ	05-09-11	10
6	Stores	Identify + stock	LE	05-09-21	7
7	A/C	cost part 47.73 47.75	Sucos	05-10-14	7
8	DC	close w/o Inspect Level 21	Poslinda	05/10/14	7

Rev	Date	Change	Revised By	Approved

DRF
SHORT rev

ISSUE